

Paula Gómez, Elliot Simon, Mike Courtney

# Guidelines for the usage of scanning lidars for power curve verification


# Motivation




Image: researchgate.net



Image: zxmeasurements.com



# Contents



<https://www.carbontrust.com/our-work-and-impact/guides-reports-and-tools/guidelines-for-scanning-lidars-for-power-curve-testing>

2.	Lidar requirements .....	7
3.	Wind field reconstruction .....	8
3.1	Using scanning lidars for standardized measurements .....	8
3.2	Recommendations for scanning parameters .....	9
4.	Calibration .....	10
4.1	Introduction .....	10
4.2	Calibration of beam position quantities .....	11
4.3	Horizontal wind speed calibration .....	13
4.4	LOS speed check .....	20
5.	Combined uncertainty of the scanning lidar in the application .....	20
6.	Measurement campaign preparation .....	21
6.1	Pre-campaign preparations .....	21
6.2	Measurement setup .....	23
6.3	Wind direction measurement sector .....	25
6.4	Post-campaign considerations .....	26
7.	Measurement procedure .....	26
7.1	Scanning lidar operation/monitoring .....	26
7.2	Wind Field Reconstruction .....	27
7.3	Data corrections .....	27
7.4	Consistency/plausibility checks .....	27
7.5	Data filtering and analysis .....	29
7.6	Measurement height .....	30
7.7	Air density measurements .....	30
8.	Reporting requirements .....	30

# Lidar requirements

- **Physical** – footprint, transport, craning, water+salt, power
- **Performance** – ppi and hard target, ranges, angles, speeds
- **Accuracy** – indicative standard uncertainties – 1.5% speed, 10m range, 0.1° angles
- **Operational** – lens cleaning(!), network, auto-start, logging of important things
- **Optional** – remote power cycle, data transfer, flat surface on the scan head, lock

# Wind Field Reconstruction (WFR)

## – keep things the same!

- Scanning lidars are really not very suitable for standardisation!
- Need to keep things as constant as possible between **calibration** and **application**, especially:
  - External processing software
  - Scanning trajectory
  - Pulse configuration
  - Acquisition time
  - Beam focus position
  - Measurement range
  - Beam elevation angle

# Recommendations for scanning parameters

- Measure preferably at **one height**, and **never more than 3**
- Use an **arc-scan sector size between 40° and 90°**
- Scan at **1-2°/sec** in **one direction only**
- Aim for **at least one completed ppi scan per minute**
- Set the **beam focus** at the **target measurement range** (if you can)
- Use a **medium pulse length/duration** (100m/300ns)
- Try to make **radial speed measurements for every 1° of arc**

# Calibration

## Beam position quantities

- Pitch and roll inclinometers
- Scanning head homing position
- Measurement range check



- PCV:**
- Correct levelling and installation
  - Inputs to PCV uncertainties

## Horizontal wind speed calibration

- Site requirements
- Setup requirements
- Lidar installation and configuration
- Data processing, filtering and results.
- Uncertainty




- Basis for PCV uncertainties

## LOS speed check

- (valuable) additional check
- Similar to IEC 61400-50-3
- If significant deviation → investigate before continuing

# Campaign preparations

- Identify suitable position on transition piece:
  - Unobstructed view, stable position, hatch access, cable routing, personnel movement
- Prepare (assemble, calibrate, pre-configure):
  - Lidar, data logger, power & network infrastructure, camera, mounting hardware, survey equipment
- Obtain permissions for site work
- Setup time-sync, remote access & data pipeline
- Take pictures!
- After installation
  - Level the lidar using the zero-tilt inclinometer calibration values
  - Measure the instrument and hard target positions
  - CNRmap hard target to determine North-aligned azimuth offset





# Measurement campaign

- Wind measurements can begin once the system is levelled & aligned
- Closely match the setup used in the onshore calibration
- Configure scan trajectory based on our suggested parameters
- Repeat lens wipe, hard target, and sea surface scans throughout campaign
  
- Monitor the devices and data collection daily (also automate checks)
  - Power & comms, humidity, range, scan config, disk usage, time-sync, tilt values, etc.
- Perform routine data checks (i.e. gaps, signal quality, beam angles, reconstruction result)
- Keep campaign logbook to document operational issues
  
- Plan decommissioning & post-campaign activities from the start
- Before removing equipment, check alignment and take pictures of everything
- Ideally, repeat the onshore work, i.e. post-campaign calibrations

# When does it make sense to use SL for PCV?

- When the required measurement distance ( $2.5D$ ) is close to or greater than a nacelle lidar range.
- In cases where nacelle access is difficult or roof space is small.
- When there are other measurement goals in the campaign besides PCV.

DTU

