DISCUSSION.

DR. M. I. PUPIN:—Mr. President, I do not think that there is much to discuss in connection with this paper. There is so much difference of opinion, and there naturally must be a great deal of difference of opinion in things depending on individual taste. The old Latin proverb, "*De gustibus non est disputandum*," applies eminently well to the design of any apparatus. The designing of machinery is a work of art, as well as of pure reasoning. A man may master the science of electricity and yet not be able to design a completely satisfactory piece of apparatus, because he lacks the artistic element. It is a thing that cannot be taught. It is just like the saying of the Greek philosopher Socrates, that you cannot teach a man virtue. It is a thing that has to be born in a man, and then developed by experience. The art of designing machinery has to be learned by practical experience, and a man will profit by his practical experience, and become a master of designing only if he has a taste for it. The experience will develop that which is in him. If he has it not in him, all the teaching in the world, and all the experience will not carry him very far. For that reason, I think, instructors in colleges do not insist very much upon the theory of design, because there is no clear cut theory relating to it. You have a theory of electricity. There are the fundamental principles and their generalizations, and you have the materials, and a man has to know the properties of materials and to combine his knowledge of electricity with his knowledge of materials to produce a method of design, and each man will have a different method; his own method of designing, but of course, all these different methods will lead to the same result. You see in this paper a calculation of what should be the dimensions of a transformer that should have the least loss. Taking a Westinghouse transformer as an example, it is found that this transformer has much less iron than this paper recommends. In another case, that of the Mordey transformer, a different relation is found. Again, the author finds that the thickness of the iron plates should be $7\frac{1}{2}$ mils, and Prof. Bedell finds that it should be 16 mils. I think the American practice is to use 12 mils. So who is right? Probably they are all right, for each one of them had different conditions to fulfil, and it is impossible to design a transformer which will satisfy all conditions. On the whole I do not think that this paper will lead to anything that could be used as a standard for all cases. But at the same time it is a very good thing to have in a paper like this, filed away in our TRANSACTIONS, and ready for reference, the various steps, the essential steps of reasoning that a man has to go through in designing a transformer. We certainly who teach in colleges are very glad to have such a reference, because it saves us a great deal of tedious discussion. A student comes to us and says: "What am I going

to do about this transformer design? What is the next step to take?" The teacher, you know, in a great many cases is not quite sure what the next step is, and he does not care to display his ignorance before the student. So he feels very much like saying to the eager student: "you will have to look that up in the electrical literature." I must say that so far, in electrical literature, there never was a convenient reference of this kind. The college professors of limited experience in transformer design (and their number is very large) can now say to students: "Read Mr. Carter's paper; it will give you all the essential points in transformer design." It takes a great deal of unnecessary, disagreeable work out of our hands; and it is disagreeable, to be sure, because not every teacher can be expected to know all the details of electrical apparatus design. Unless a man has been employed in some factory and made his living by designing, he cannot be expected to know much about it. As a mere scientific study the thing is dreadfully uninteresting. But it is a necessary evil, and very necessary indeed. In fact the success, sometimes of a company, depends on the appropriate design of its machinery. I was told some time ago that a man who was connected for a long time with a large electrical manufacturing company, stood very high with the company because he was a most eminent designer. He could design better than anybody else because he was a born artist in matters of design. That man could tell you more about a machine by merely looking at it than an ordinary electrician could by elaborate tests. The success of the company in a great measure depended on him. That shows how necessary a thing it is—this work of designing which to many of us appears dry. We ought to be very grateful to Mr. Carter for having taken the trouble to put down in this admirable, systematic way, the method of designing a transformer; and I only wish that somebody else who has had a large practical experience would come up and tell us all about designing an alternator, synchronous motors, induction motors and all that sort of thing. We would then be in a very fair position to train our young men and to develop their latent faculty of designing.

PROF. W. S. FRANKLIN:—I wish to express my concurrence with the views of Dr. Pupin in the matter of teaching transformer design to students. The "cut and try" method is no doubt the method of practice, but it is not a method which lends itself with any convenience whatever to teaching. We have not had heretofore a mathematical statement of the principles of proportioning transformer parts, or in short we have had no method of design. We have known indeed precisely how transformers act, we have known how to calculate the secondary turns when the primary turns are given, we have known how to calculate losses, regulation, and every item of their behavior, but these are only the foundations of designing, and it seems to me that Mr. Carter's paper is the first that has been given on transformer design.

I may be permitted to say further that a consideration of limiting cost might easily be formulated and used in connection with Mr. Carter's method for determining rationally the absolute size of a transformer, instead of the choice of an arbitrary current density in the coils. This formulation is outlined as follows:

The cost, \$, is approximately:

$$\text{\$} = ac + bi$$

where c is the weight of copper, i the weight of iron, and a and b are constants. The interest charge is proportional to \$ and may therefore be written

$$\% = a'c + b'i.$$

Take, now, Mr. Carter's expression for total loss, W , in terms of the yet undetermined dimensions of the transformer. The yearly value, Y , of this loss is at once known in the terms of the value of power, and the yearly total cost of the transformer is $Y + \%$ which is completely expressible, as above stated, in terms of the various items of the yet undetermined design, and these various items may then be determined so as to make the function $Y + \%$ a minimum. In this way the design would be determined without any arbitrary basis whatever. This method would always give a cheaper transformer than the transformer of maximum efficiency.

MR. W. B. JACKSON:—It seems to me that we have been discussing this matter wholly from a theoretical standpoint without giving sufficient consideration to its practical bearing. Having had some experience in the designing of transformers I feel competent to say that it is a mistake to suppose that the "cut and try" method is that now used exclusively in practice. When the transformer was made by the old uncertain methods we did not have what would be called, at present, a transformer at all; it was merely a bunch of copper and iron, and we were fortunate if able to make a reasonably good guess of the resultant action; it could not be calculated. When the transformer was made a reliable machine, it was by means of the most careful calculations, no less than we are requested to make in the paper we are discussing, and now when a transformer of a new design is brought out by a competent designer we feel assured if he has set himself the task of determining the loss in copper and in iron, the leakage current, and the drop, that when the transformer is completed it will very closely fulfil the conditions. The greatest difficulty, to my mind, we have not taken up to-night, and yet it is one that daily confronts us in practice, that is, the *heating* of the transformer. This must always be a determining factor in the proportioning of the copper and iron whether considered from a purely theoretical, or from a practical standpoint. Those who have made practical use of the various kinds of transformers now on the market have found a great part of the trouble experienced with them to be caused by defective design of the electrical and magnetic circuits considered apart from the insulation and build-

ing up of the apparatus; in some cases the copper heating too greatly for the normal load, and in others the iron. This fact demonstrates the futility of designing a transformer without due consideration of the heating factor.

Mr. Carter handles the subject most ably, theoretically, but of what value is the theoretical discussion unless it has clearly a practical bearing? Why should we not touch upon some of the principal points that interest those of us who have left for the time the designing of such appliances, and have taken up the use of them? There are one or two points of vital interest to every one of us who has to put a transformer on a pole or into a hole; for instance, shall we use an oil or a dry transformer? Also, how much added capacity do we get in an oil transformer over a dry one? Now these are points that are really worth careful investigation but, as far as I know, have never been taken up in a scientific manner, never having been worked out completely.

I know this, that where I can overload an oil transformer 10 per cent. without oil, that if I put in oil I can get just about as good results with an overload of 50 per cent. But is there any one here who has made the necessary tests to show us how much more capacity a transformer has when it has oil in it than when it has none? And should we, to get the best results, have the copper and iron in different proportions when designing for the use with oil or with no oil?

To my mind a design is not worth considering unless it is practical in the most thorough sense. I am a college man and I value very highly my college training, but I think our young men are not made to realize the practical significance of what they are taught; for instance, that such calculations as those of Mr. Carter's paper are of absolute importance, and that in our foremost electrical shops the result of formulæ just as complex as those of Mr. Carter are used in the successive steps of the manufacture of the transformer.

It is surprising that at the present day so many transformers are put upon the market that are not well designed. I can give a little experience in regard to one that was brought to my notice in the northwest. The manufacturer asked me to measure the leakage current. He said his transformer was "a dandy." I found it had over ten times as much leakage current as a standard transformer should have. At a low price this was a very expensive transformer. There are others equally expensive, and it is necessary to realize the importance, in buying, of choosing those of known low waste of energy.

I was interested to hear Prof. Franklin speak of this paper as probably not being worth very much because the Westinghouse transformer comes so near it in its calculations. But I think the paper is no less valuable because one make of transformer is similar in calculations, since there are hundreds of other makes that ought to be benefited by it.

There are several other questions relating to this subject that I should like to have discussed. I suppose all of us who are engaged in the electrical business have heard the question from a manufacturer "How much drop can you stand in your transformer?" "How much watt leakage?" As far as I know the answer can only be approximate. Can any one tell me what the drop *should* be? I do not see why our discussion should not take up both theory and practice. I suppose there are others interested, as I am, in considering this subject from all sides.

MR. TOWNSEND WOLCOTT:—The question as to whether transformers in use to-day are designed by "rule of thumb" or not seems to be still open. I know within the last year or two I have seen several statements, especially from English electricians;—(I think one was Mr. Swinburne, another was Prof. Fleming)—that owing to the fact that there is no simple mathematical expression, in fact even a complicated one, for the relation of magnetism in iron to the exciting current, it is impossible to design a transformer entirely on a scientific basis; the design is practically "rule of thumb." On the other hand, some other electricians, more particularly Prof. Carhart, last year said that he gets practically accurate results by assuming the sine form of wave of magnetism. In the first place, he may not have exactly a sine current, but assumes a sine form for both the current wave and also the wave of magnetism, and he says he gets results that are as accurate as you get in direct current machinery. It would seem that the "rule of thumb" practice is going out of designing at all events, if it is not already out.

PROF. FRANKLIN:—Mr. President, if I may impose upon the good nature of the INSTITUTE yet a few moments more, I may be allowed perhaps to say a word on that matter, as to what the design of transformers consists of at the present time. It seems to me—of course, I don't know very much about it, I will admit that—but it seems to me that the thing we know about transformers and the thing which practical men know about transformers is *how transformers act*. After a transformer is made, after you have decided upon the items in its design, you can calculate the ratio of electromotive force, you can calculate the magnetizing current, you can calculate the hysteresis and eddy current losses and the ohmic losses and all the details, without exception. That of course constitutes, as matter of fact, the basis of the paper to-day. Mr. Carter takes all that for granted. But the designing of a transformer is a matter of correlating these various items, and I think there can be no question but that the design heretofore has been a "cut and try" method of correlation and not a rational method of correlation. Of course it is not a matter of a single designer's beginning with Adam and working his own "cut and try" himself. He makes much of the practice as it exists at the present day, which represents the results of all the cutting and trying which has been done

before him. A designer at the present time perhaps loses sight of the fact that the real essence of his design is "cut and try," because he does not carry out all of the cutting and trying himself and he is inclined to think that his knowledge of the action of the transformer is what he uses in designing. I think not. I think that he uses this merely in calculating what the transformer will do after he has designed it. Then he will design another with say two or three more turns of copper, and he will calculate what that will do. Then he will design another with two or three more sheets of iron and he will calculate what that will do. If that is not cutting and trying I don't know what cutting and trying is. Of course I may be mistaken in supposing that practical men design transformers in that way. I have designed a good many transformers, but they never were built, you know, so I cannot say anything from a practical point of view.

I cannot withstand the desire, Mr. President, to say one thing more, not in direct connection with the subject in hand, but in connection with the remark which was made by Mr. Jackson. He said that college men do not teach the actual practical methods of engineering, and the actual practical significance of the various points they take up. Now I think that as a rule no class of men understand better the worthlessness of what they teach than college men themselves. I think they appreciate the truth of a remark, if I may be allowed to quote German—a remark which occurs in Goethe's Faust, where Mephistopheles turning gravely on a student who has just come to confer with the professor: "Gray, my dear friend, is all theory, and green only is the tree of life."

DR. PUPIN:—If I may be permitted just to say one word more, I would like to supplement the quotation that Professor Franklin has made with reference to the teaching of design. Faust also says:

*"So muss ich dem mit saurem Schweiss
Euch lehrn, was ich selbst nicht weiss,"*

which I can translate for you in English, but of course not so as to produce Goethe's classical rhythm—"And so with the sweat of my brow I must teach you what I do not understand myself."

As far as I can see, this paper is just as practical as it can possibly be. It is limited to the design of a transformer under perfectly specified conditions. It does not speak of the oil transformer, because that is a separate matter. I do not see why the question of enclosing the transformer in oil is any more practical than the subject that this writer has discussed. Everything is practical, but of course we cannot take more than a certain number of steps at a time, and after we have taken those steps securely and safely we can take the next step. The question of whether we enclose the transformer in oil or not, is no more practical than giving the transformer the proper dimensions. A previous speaker admits that we consider also when we take up this ques-

tion of oil: will not oil dropping from transformers hung upon poles, on the clothes of people bring the company into difficulties? That is a very practical question, but it is hardly within the limits of design. It brings in social questions and legal questions. In this connection it might be well to repeat a story told concerning a strange experience with the experiment in conveying power from Lauffen to Frankfort. The original design was all right, that is, the engineers thought it was all right, but they found it was all wrong, the thing would not work; and when they came to examine it they found that they made a mistake in making the insulators white, because the little boys in the fields had their attention attracted to those white insulators and thought they were good marks to throw stones at, so they threw stones at them and broke them, and that affected the whole plant and caused a tremendous leakage. The insulators were painted gray and the trouble was over. Well, that is hardly within the limits of designing conductors to transmit power, and yet it was of vital importance. At some date it may be of very great importance to know whether we should paint our transformers hung up on a pole, green or red or gray, but if we do it will be owing to some psychological or perhaps political reason. All questions are practical, but of course certain questions are more directly within the limits of transformer design than others, and I would not blame Mr. Carter for not spreading himself too wide. I think he has spread himself wide enough as it is.

MR. JACKSON:—I think I ought to say a word or two more, perhaps; Professor Pupin has not taken my meaning. I think what I said was, that this paper although theoretical was of practical value. I took issue with Professor Franklin in saying it was not practical. I think every figure in the mathematics used in designing a transformer is of practical value, and it is an interesting fact that our best transformers are based on very careful and minute mathematical calculations. I think also that Mr. Carter developed his theories far enough but why should we not apply them? The theoretical is so intimately related to the practical that we must have both to carry on a really valuable discussion. Why must we accept the mathematics and then drop the discussion? Up to within a comparatively recent time my business has been in connection with the designing of transformers and generators and similar work, consequently I am intensely interested in everything relating to these subjects.

I want to go a step farther than these discussions usually carry us and ask this society to help us who are working in practical lines to more definite knowledge. When I am told that a certain transformer is the one that will completely satisfy me and I state my objections to it I am not sure that I am right. I want such information that I can be absolutely certain that my opinions are properly based.

I have a very great respect for our college professors and their

work. I think it is to them that we owe the fact that the number of well trained engineers is large, and is constantly increasing. It is up hill work for a man who has had no technical training to compete with the college trained man. But there is one thing in which the college is somewhat wanting, sufficient practicality. As I used to question in my calculus class, where is it possible that the "differential X" can be used in practical life? When out of college this question was soon fully answered and my only regret is that I could not realize its significance while under training. I believe more attention is now given to practical applications in college, and our later college graduates will be prepared to surmount difficulties that puzzle some of us older ones, but that will help us but little, and therefore I call upon our society to take up practical questions more fully in connection with the theoretical.

MR. WALTER S. MOODY:—As one who is actively engaged in every day practical design, I would like to make a few remarks.

First, I can assure these gentlemen who question the amount of use that is made of theory in every day design of electrical apparatus, that as far as my own work is concerned all the theory that college men develop for us finds ample use in every day practice.

There is no class of electrical apparatus designed to-day, I believe, by the best companies, whose proportions are not just as carefully analyzed as Mr. Carter's paper analyzes transformer proportions. But, of course, there are a great number of practical difficulties and considerations that modify the purely theoretical formula, or, more correctly speaking, our theoretical formula cannot be broad and complicated enough to include all the actual conditions presented. Mr. Carter's paper, for instance, while very complete on the points considered, leaves entirely out of consideration such essential facts as might entirely overpower the importance of the features which he discusses. Perhaps the most important factor which Mr. Carter does not in any way refer to is the question of heating, and the necessary radiating surfaces to dispose of the losses within the transformer. It would be perfectly possible to apply the formulæ developed by Mr. Carter, and which in themselves are undoubtedly perfectly correct, and yet obtain a design entirely impractical because of the lack of the necessary radiating surface to dispose of the heat.

Again, Mr. Carter's calculations all contain a constant which he designates as " p ," and which expresses in per cent. the relation between the cross-section between the primary and secondary copper and the area of the wire space. In the calculations this figure is assumed, or rather it seems to be based on the actual per cent. found to express this relation in the transformers under consideration. Of course, in actual design this question has to be given careful study in order to make the percentage as

high as possible, and still get the necessary insulation and the best distribution of it.

What I would like to bring out is that there is really great latitude in the choice of the best proportions for transformer design. One who has carefully figured the proportions of any piece of electrical apparatus, applying to the design a most careful analysis as to its proportions, and who has satisfied himself that he has a most thoroughly designed piece of apparatus, will often be surprised and disappointed to find that some one else's design which has been less carefully calculated, or perhaps worked out entirely by the "cut and try" method, is, as far as its proportions are concerned, nearly or quite as good as his own carefully developed design. In other words, as Mr. Carter himself points out at the bottom of page 667 of his paper, quite large changes in the proportions of the various dimensions of the transformer designed, affect but slightly the final results obtained, and consequently more practical considerations make advisable, or even necessitate, marked departures from the most economical proportions.

While I have not had an opportunity to carefully study the paper, yet I have hastily checked up some of the proportions found based on Mr. Carter's study with actual transformers of which I know the proportions, and find that these transformers had dimensions differing in their relation some 200 or 300 per cent. from those which the paper showed to be the most economical, yet these transformers are even more efficient (considering the value of the material in them) than the transformer which Mr. Carter develops to illustrate his formulæ. In other words, considerations which are in one sense purely details of shop practice or skill in workmanship, may modify the results to such an extent as to entirely outweigh the consideration of best theoretical proportions.

While I am speaking, I trust I may be pardoned for answering one of the more practical questions brought up by Mr. Jackson. I refer to his question as to the value of the use of oil in transformers. This is a question which has always been a subject of much discussion, and is one which sometimes is almost as hard for the manufacturer to settle as for the users of the transformers to decide upon. Many factors enter to determine one's decision in this matter, but in general it can be safely said that the use of oil transformers has vastly increased in the past few years.

The question as to just how much the capacity of the transformer can be safely increased by the use of oil is not one subject to direct answer, because the value of oil varies so much with different designs of transformers. Of course, we all understand that oil acts in a double manner in increasing the capacity of the transformer; first, by excluding air, and thereby preventing oxidation of the insulating material, and consequently

increasing the temperature at which the transformer may be safely operated, and second, and more important, it acts as a heat conducting medium to carry the heat generated in the transformer to the transformer case. The space between the transformer and the case is small, and the air within this space consequently is too confined to allow any great amount of circulation, and therefore it acts as a poor conductor of heat. Oil will move much more freely under a slight difference of temperature, or, perhaps more correctly speaking, its specific heat is so much greater than that of air, that even with a slow motion it acts much more efficiently in conveying heat to the enclosing case. Just how much however oil will increase the safe capacity of a transformer can only be answered for each size and design of transformer independently. A small transformer may not have its capacity appreciably increased by its use, whereas a large one lacking in radiating surface on the coils and iron, but having a large exposed surface in its case, may easily have its capacity doubled, or even trebled by the use of oil.

THE PRESIDENT:—While we are indebted to the author for presenting to us propositions concerning the efficiency of a transformer, which are capable of analysis and application, it seems important to bear in mind that these propositions are necessarily limited by the conditions stated in their enunciation, and that many other conditions must be taken into account in the design and operation of commercial transformers. The deductions from these propositions probably require considerable modification to suit different conditions of practice. Cost, size, weight, excitation current, magnetic leakage, regulation and heating, are some of the factors which must be included in the design of a good commercial transformer, and the relation between these factors is so complex as to elude a general mathematical formula of design. Consequently, while I do not wish to undervalue the rules given in the paper for determining the design of the most efficient transformer, it seems important to bear in mind that the question of efficiency is not the only one which must be considered in practice, and that after all such rules have been taken into account, the method of trial and error must always be depended upon in arriving at the best design of a transformer at the present time.

MR. PHILIPPO TORCHIO:—Mr. President, one point which has not received attention in the discussion is on page 657, where the author alludes to the condition of work for which the transformer is designed. It is very important for the central station manager to get a transformer that will be most efficient under its special conditions of use. The author has in this diagram the daily load in amperes and also the ohmic transformer losses, proportional to the square of the amperes. The whole day ohmic losses represent a smaller or larger proportion of the total trans-

former losses according to the use of the transformer. If the transformer is going to operate at full load, say one hour a day, and be idle for 23 hours, the ohmic losses will be comparatively small; but if it operates 24 hours a day at full load, these losses will be large. Therefore, from the central station point of view, one transformer designed for a certain condition will not do as well under another condition. I think that this point of the load factor of the transformer is worth considering in the design of transformers. Of course, besides the condition of regulation, the cost of the transformer should also be included in the problem, together with the cost of energy in each special case, as the central station can afford to increase investment cost when the coal and running expenses are high; but when these are low, as, for instance, in water-power plants, the inducement is to reduce investment cost. I think this point of the transformer load factor brought out in the paper is very important for the design of the most economical transformer for actual operation.

MR. F. V. HENSHAW:—I think the last speaker has brought out a very salient point there in practical work, because I should rather imagine that most transformers are sold on their no-load consumption of energy, because if you get a transformer which wastes very little energy when the secondary is open, you will meet the conditions that probably at least nine-tenths of the central stations have, and for that reason it seems a little significant to me that the author finds the Westinghouse transformer has half as much iron as the "most economical design." While I have not gone into the thing very deeply, it seems to indicate that the author is going for full load efficiencies, rather than minimum wasted energy at no load, and in that case it is somewhat questionable whether the formulæ which we have every reason to be thankful to the author for putting in such good shape, could be followed in practical work with entire success. It seems to me rather, from the practical point of view of selling transformers to central stations, that we ought to have one that would run with very small light load losses and very small hysteresis losses, while at full load the ohmic losses might be as high as they could possibly be made without burning up the insulation. I do not know whether that is treating it very scientifically, but it seems to me it is rather a practical way of looking at it.

MR. JAMES HAMBLET:—Mr. President, I have been very much interested in the discussion this evening. I think it has been truly valuable in one sense more than in any other. Many of us present noticed two or three years ago quite an undercurrent of criticism unfavorable to the extreme mathematicians of the INSTITUTE. There has been, I think some will remember, quite a complaint coming to the surface, and a great deal of talk was made that we had too much mathematics. I want to congratulate

those present, Mr. President, on the fact that we have seen evidence to-night of some harmony of feeling between the extreme mathematicians and the practical engineers. I move we adjourn.

[The motion was carried and the meeting adjourned.]

[REPLY COMMUNICATED BY THE AUTHOR.]

I will endeavor briefly to reply to some of the points that have been raised in the discussion on my paper. The chief objection that has been made to my method of design, is that it does not take account of certain practical considerations, such as the cost, the exciting current, etc., which, if they were discussed, might render useless the formulæ I have given. I should certainly have gone into these and other questions, had it not been that the paper was already lengthy, a fact which induced me to limit it to the consideration of its characteristic feature,—the direct method of design to give maximum efficiency. Some of the points, however, are mentioned in the introduction and shown to be implicitly taken account of by the method; others are more or less involved in the maximum current density assumed. In general, however, it would not be advisable to prescribe these quantities, but rather to give their limiting values; thus if the magnetic leakage is not excessive, it does not much matter what it is. Again, designers seem to be quite at variance as to what these limiting values should be. The table given on page 679 of the paper, enables one to see this immediately. The cost, weight, and size, of the Westinghouse transformer, are less than those of the two transformers corresponding to it, but of the Mordey transformer they are greater than those of its corresponding two. The exciting currents are probably less in my transformers than in the others; at any rate, they convey less power, as the no load losses are less. The magnetic leakage will be greater in the Westinghouse, and less in the Mordey than in my transformers, for the same subdivision of the coils. The regulation of the Westinghouse will not be as good as in my transformers, whilst that of the Mordey will be somewhat better than one of mine, and hardly so good as the other. The radiating surface per watt, is greater in mine than in the Westinghouse, and less than in the Mordey. Although the Westinghouse and Mordey transformers differ in output, they are nevertheless two ordinary transformers, by well credited makers intended to work under about the same conditions. Their respective designers, however, evidently had very different ideas as to the proper values for these supplementary quantities, so that the importance of the latter cannot be sufficient to render useless a method of design which need not bring any of them into objectionable prominence.

The modification of my method indicated by Professor Franklin,—that of including the interest charge on the outlay among the losses,—is certainly the most scientific way of performing