



Settings only if the IR spectra are not presented properly on the relevant area

1. Go to Control panel and then click select region.



2. Click additional settings



3. Change the decimal symbol to dot "." and the digit grouping symbol to comma ",".

