Evaluation of Water Quality Impact Caused by Common Hazardous Waste Landfill Facility in Gummidipoondi, Tamilnadu- India

D. Vasudevan, A.G. Murugesan

Abstract: *The aim of the study was to evaluate the water quality impact caused due to the operations of common hazardous waste landfill facility (CHWLF) in Gummidipoondi industrial estate, Tiruvallur district, Tamilnadu, India. The watershed area of the hazardous waste landfill facility was delineated using Arc-GIS tools and prediction of ground water flow direction was carried out using three-dimensional ground water flow model using VISUAL MODFLOW software. The water quality analysis was performed in the upstream and downstream directions of the project site and the results showed that all the tested parameters were within the BIS 10500:2012 drinking water limits, except pH which showed slightly acidic characteristics in certain locations. The tested water samples mostly belonged to the Ca + Mg-HCO3' type as classified using the multivariate analysis method using piper diagram. Co-relation between the water quality parameters were determined using statistical analysis of Pearson's correlation coefficient (r) values.*

Keywords: *Common Hazardous Waste Management Facility, Landfill, Water Pollution, MODFLOW, Impact Assessment, Ground Water Contamination.*

I. INTRODUCTION

One of the major concerns of industrial developments are the problems associated with hazardous wastes that are often generated as by-products during industrial manufacturing process. The wastes regardless of its volume are known for its toxicity, which when exposed to environment are known to bring harmful and irreversible damages (Burge and Rogers, 2000; Dongo *et al*., 2012; Fazzo *et al*., 2017; Misra and Pandey, 2005).

As per the Hazardous and Other Wastes (Management &Transboundary Movement) Rules, 2016, hazardous wastes are defined as those wastes 'which by reason of its characteristics, such as physical, chemical, biological, reactive, toxic, flammable, explosive or corrosive, causes danger to health, or environment'. The widely adopted approach in India for handling and disposal of hazardous wastes is disposal through a common hazardous waste management facility (Vasudevan and Murugesan, 2017). The common hazardous waste disposal facilities are known to offer an integrated approach for transportation, storage, treatment, and disposal of hazardous wastes for the industries. The disposal is carried out largely through engineered landfills and incinerators (CPCB, 2016). Though the methods provide a formalised and streamlined approach for managing hazardous wastes aiming to contain and treat the wastes in a secured manner, the approach still poses potential threat due to improper operation and maintenance, and accidental release of hazardous substances through such facilities. The limitation of hazardous waste landfills is its potential to contaminate ground water sources, whereas the operation of incinerators may cause air pollution due to improper combustion of toxic organic compounds and its release into the environment (Vrijheid, 2000, Ying Li et al, 2012, Yang et al., 2016).

Technically, the International Solid Wastes Association (Bagchi, 1994) defines landfill as "the engineered deposit of waste onto or into land in such a way that pollution or harm to the environment is prevented, and through restoration of land provided which may be used for other purpose". However, the disposal of wastes in landfill sites is a matter of concern due to possible generation of toxic leachate and the potential ground water contamination that could take place. Leachate is produced when rainwater percolates through various layers of wastes and is influenced by biological and chemical reactions within a landfill. The leachate thus comprises of complex and concentrated organic, inorganic compounds and heavy metals which have a high potential to cause adverse effects to humans and environment by contaminating ground or surface water resources (Kumar and Alappat 2005).

The generation of leachate depends on several factors including construction, operation, and maintenance of the landfill facilities. When the above steps fail to meet the required standards of performance, groundwater contamination due to leachate or mishandling of hazardous waste may take place which will also be influenced by several other parameters such as soil permeability, hydrological conditions of the site and directions of ground water flow. This is a major concern as the water pollution causes adverse health effects for populations living nearby, particularly in relation to those sites where hazardous waste is dumped (Kubal *et al*., 2003, Press 2016).

D. Vasudevan*, Research Scholar, Sri Paramakalyani Centre of Excellence in Environmental Sciences, Manonmaniam Sundaranar University, Alwarkurichi (Tamil Nadu), India .

A.G. Murugesan, University Grants Commission Faculty Fellow Sri Paramakalyani Centre of Excellence in Environmental Sciences, Manonmaniam Sundaranar University, Alwarkurichi (Tamil Nadu), India .

One important tool for assessing effective management of hazardous wastes in CHWLF and avoiding its risks of pollution is through evaluation of its environmental impacts. It helps identifying any pollution caused by the facility in early stages thereby enabling to perform pollution mitigation measures and keeping its harmful effects under check.

In recent years, geographical information system (GIS) based tools are gaining increased application for environmental impact assessments including research on groundwater assessment and management (*Singha Sudhakar et al. 2016*). GIS tools can easily access overlay and index operations and can represent real scenarios through integrated layers of constituent spatial data (Corwin, 1996). Coupling GIS technology with a process-based groundwater model facilitates conceptualization of hydro geological and hydrologic system and its characterization (Hinaman1993; Kolm1996; Gogu et al. 2001), thus enabling a proper adaptation of the groundwater flow model to the study area (Brodie1998). Chao-Shi Chen,et al.,2016 used the groundwater modelling systems software, to numerically model groundwater flow and contaminant transport for the Wang-Tien landfill site in Taiwan. The simulation results showed that the total mass of pollutants in the aquifer increased by an average of 72% for a duration of 10 years. The spatial extent of the contaminant plume was also reported that spread to 80 m in length and 20 m in depth north eastward from the landfill site. Similar application of groundwater model was demonstrated by O. Ganesh Babu *et al.*, who assessed the aquifer vulnerability of Noyyal River basin using Visual MODFLOW– MT3D. The study helped in delineating potential contamination zones as an effect of pollution caused by industrial effluents from textile industries. From the above observations and similar studies carried out by other researchers, it can be inferred that the combination of GIS and ground water models such as MODFLOW offer promising ways to predict contaminant transportation in subsurface waters, thereby flagging vulnerable areas facing high risk of pollution. Predicting and identifying vulnerable areas of pollution can help the stakeholders in preparation of suitable mitigation plans for prevention of pollution and its harmful effects.

In line with the above research works, the present study aims at evaluating the environmental impacts on ground water quality associated with the operation of a common hazardous waste landfill facility (CHWLF) in Gummidipoondi industrial estate, Tiruvallur District, Tamilnadu. The objective was to find out the impact on the groundwater quality with the help of GIS tools and carry out real time monitoring to check the presence of any pollutants in the groundwater.

II. METHODOLOGY

2.1 Study Area

The common hazardous waste landfill facility (CHWLF) extending over 9 acres, bounded by longitudes of 80° 06' 23" E and 80° 06' 27" E and latitudes 13° 24' 47" N and 13° 25' is in the State industries promotion corporation of Tamilnadu (SIPCOT) industrial complex, Gummidipoondi taluk of

Thiruvallur District, Tamilnadu, India. The facility is in operation since 2007 with an engineered landfill with a handling capacity of 180 thousand tons per annum of hazardous wastes. So far around 5 lakh MT of hazardous wastes has been disposed in the landfill facility.

Area covering about 10 km radius around the landfill site with 23 monitoring location was evaluated for ground water pollution. Within the study area, the watershed of the project site was established by defining lineaments using ARC GIS techniques. The delineated watershed map encompassing the areas of natural preferred pathways of contaminants from the potential contamination zone is provided for reference in Figure 2. The details of the sampling locations are furnished in Table 1.


**Figure 1. Map showing monitoring locations over 10 km radius from landfill site**

Figure 2. Delineated watershed area comprising the project site.

Table.1 Sampling locations for ground and surface water monitoring

Code	Name of the locations
GW 1	Project site
GW 2	Pappankuppan East
GW 3	Gummidipoondi new
GW 4	Chintalakuppam
GW 5	Nangopallam
GW 6	Nethaji Nagar
GW 7	Tervazhi
GW 8	Periyasoliyambakkam
GW 9	Raghavareddimedu
GW 10	Sirupuzhalpettai
GW 11	Peddikuppam
GW 12	Thambureddipalayam
GW 13	Verkadu
GW 14	Gummidipoondi Old
GW 15	Chinnaobulapuram
GW 16	Aathupakkam
GW 17	Narasinghapuram
GW 18	Valuthalambedu
GW 19	Karambedu
GW 20	Enathimelpakkam
GW 21	Natham
GW 22	Rettembedu
GW 23	Annapanaickenkuppam

2.2 Groundwater Modelling

In the field of groundwater flow modelling, numerical simulation models are employed to describe hydrologic phenomena such as groundwater movement. The main purpose of such models is to predict the direction of groundwater and solute movement, which play a significant role in understanding contaminant transportation. In the present study a hypothetical model was simulated using the finite difference model of Visual MODFLOW- 2000. The partial-differential equation of groundwater flow applied in MODFLOW (Harbaugh et al, 2000, McDonald and Harbaugh 1998) is

$$\frac{\partial}{\partial t}\left(K_{xx}\frac{\partial h}{\partial x}\right) + \frac{\partial}{\partial y}\left(K_{yy}\frac{\partial h}{\partial y}\right) + \frac{\partial}{\partial z}\left(K_{zz}\frac{\partial h}{\partial z}\right) + W = S_s\frac{\partial h}{\partial t}$$

where Kxx, Kyy, and Kzz indicate aquifer conductivity along the x, y and z axes (L T^{-1}), h: flow head (m), W: sources and/or sink of water (s^{-1}), Ss: specific storage (m^{-1}), t: time (T).

Using the visual MODFLOW software, the flow direction of ground water was predicted in the watershed area. The model results helped to identify the most probable areas of contaminant transportation which were monitored by real time analysis of collected groundwater samples.

2.3 Monitoring and Analysis of Groundwater Samples

The water quality monitoring was carried out on a quarterly basis in all the 23 locations in the study area from September 2017 to August 2019. More number of ground water sampling locations were chosen based on the predicted groundwater flow direction using Visual MODFLOW.

The various water quality parameters tested in the groundwater samples and their methods of analysis are provided in the Table 2.

The results on water quality were also compared with the legacy data documented by the National Environmental Research Institute (NEERI) in 2005 prior to establishment of the landfill facility. Based on the comparisons of data obtained between 2005 and 2019, the results on impact on water quality in the study area were assessed.

Table. 2. Water Quality Parameters analyses and methodology

Parameters monitored	Methodology
pH	Electrometric Method
Electrical Conductivity (EC)	Laboratory Method
Total Dissolved Solid (TDS)	Gravimetric Method
Total Hardness (TH)	EDTA Titrimetric Method
Chloride (Cl^-)	Argentometric method
Sulphate (SO_4^{2-})	Turbidimetric Method
Phosphate (PO_4^{3-})	Colorimetric Method
Nitrate (NO_3^-)	Ion Chromatograph
Sodium (Na^+), Potassium (K^+)	Flame Photometry
Heavy Metals (Arsenic (As), Cadmium (Cd), Chromium (Cr), Mercury (Hg), Lead (Pb), Zinc (Zn), Copper (Cu))	Graphite Furnace Atomic Absorption Spectrometric Method
Biological Oxygen Demand (BOD)	Winkler's Method
Chemical Oxygen Demand (COD)	Open Reflux Method

2.4 Chemical Speciation of Groundwater Samples using Piper Trilinear Diagram:

A Piper trilinear diagram was used to classify the groundwater samples based on the presence of various ions viz, Na^+, K^+, Ca^{2+}, Mg^{2+}, HCO_3^-, CO_3^{2-}, Cl^- and SO_4^2 (Piper, A.M. 1994, Manoj *et al*., 2013).

2.5 Calculation of Pearson Correlation Coefficient

Pearson correlation coefficient was used to understand the correlation and influence of ions between each other in the ground water samples analysed.

If x and y are the two variables, $\bar{x}$ and $\bar{y}$ are the mean of x and y variables respectively, and then the Pearson correlation coefficient (PEARSON) (*r*) between the variable x and y is given by, equation (1)

$$r = \frac{\sum (x - \bar{x})(y - \bar{y})}{\sqrt{\Sigma (x - \bar{x})^2 \Sigma (y - \bar{y})^2}} \tag{1}$$

In this study r > 0.70 was considered as a significant correlation, 0.5≤ r ≥ 0.70 as a moderate correlation, and r< 0.5 as a non-significant correlation (Qialin Zheng et al., 2017)

III. RESULTS AND DISCUSSION

3.1 Geology and Groundwater Flow in the Study Area

Watershed based monitoring was adopted in the current study as it helps in evaluating the condition of the ground water resource while also providing interlinked watershed information to help establish cause-and-effect relationships. Understanding the groundwater movement and its direction within the watershed is critical to identify the leachate movement in case of its inadvertent release and contamination at the landfill site. Arc-GIS tool clubbed with VISUAL MODFLOW was used perform a three-dimensional

groundwater flow modelling to understand the groundwater movement from the project site (Fig. 3)

a. Pre-monsoon ground water flow directions

b. Post-monsoon ground water flow directions
Figure. 3. Groundwater flow direction in a) pre mon soon season and b) post monsoon season

The hydraulic gradient in the project site was found to be moderately low and has been observed as an average of about 1.1 m/Km in pre monsoon and 0.8 m/Km in post monsoon. A litholog of the project site (Table.3), shows presence of clay upto minimum 15 ft with a permeability co-efficient of 7.03×10^{-4} cm/sec. This helps us understand that the percolation of ground water at the project site may be comparatively slow due to the semipermeable nature of the soil at site.

The ground water level in the land fill site was found to be moderately deep (<15 m bgl) both in the pre- and post-monsoon periods which suggests that the infiltrating water may have least possibility to reach the ground water table. However, to validate the above understanding a real time ground water monitoring was carried out around the landfill facility.

As suggested by earlier researchers (Brisbane, 1996), monitoring more locations in the down gradient were given more preference than in the upgradient.

Table.3. Details of litholog at project site

Sl. No	Depth (ft)	Type of soil with colour
1	5	Topsoil, Lateritic, Reddish brown in colour
2	10	Clayey Sand, Yellowish
3	15	Clayey Sand, Yellowish
4	20	Clayey Sand, Yellowish
5	25	Clayey Sand, Yellowish
6	30	Clay with little sand, Yellowish
7	35	Clay with little sand, Yellowish
8	40	Clay with little sand, Yellowish
9	45	Sand fine to medium, Quarzitic with little clay
10	50	Sand fine to medium, Quarzitic with little clay
11	55	Only sand fine to medium size

3.2 Analysis of Water Quality in the Study Area

Water quality monitoring was carried out over a period of two years year from September 2017 to August 2019 and the observations on various water quality parameters are presented below.

3.2.1 Analysis of pH

The samples were analysed for pH which is an index of the hydrogen ion concentration [H^+] in water. The [H^+] affects

Figure. 4. The spatial distribution map of pH in the study area

most chemical and biological processes; thus, pH is an important parameter in determining the water quality (Boyd *et al*., 2011). The Bureau of Indian standards 10500:2012 have fixed the pH criteria for drinking water ranging from 6.5 to 8. The average pH values of the study area are plotted in the spatial distribution map shown in Figure 4.

The results of the study showed the pH values of ground water ranging from 6.43 to 8.23. The minimum pH was observed inside the industrial estate in Gummidipoondi in the

Figure. 5. Graph showing temporal variation of pH in the study area

Upstream of CHWLF site, where pH was below the prescribed limits as per BIS standards. The maximum pH was observed in Periyasoliyambakkam (GW 8) which is in the downstream and outside the industrial estate respectively.

The graph in Figure.5 illustrates the temporal variation of pH in thirteen groundwater monitoring locations for which the legacy data were sourced from NEERI report, 2005. It was noticed that the overall pH values in the study area remained almost same, where the 2005 and the current data showed values ranging from 6.65 to 8.01 and 6.71 to 7.61 respectively. Though the above pre- and post-project data does not show any significant variation in the observed pH over a decade, the slightly acidic characteristic of groundwater in certain locations raised concerns of possible groundwater contamination caused by the existing industries upstream, where outcrops and shallow levels of groundwater are observed. Similar studies on acidification of groundwater because of leaching of ferrous sulphate was reported by Kubal *et al., 2003* during their evaluation of landfill impacts at Pozdatky in Czech Republic.

However, it is noteworthy that in recent years in India, the Central and State pollution control boards have been giving more emphasis on zero liquid discharge and to recycle treated trade effluents within the industrial processes to conserve water and thereby avoid any possible contamination of groundwater.

3.2.2 Analysis of TDS

The other important water quality parameter analysed was total dissolved solids (TDS) which is a measurement of inorganic salts, organic matter and other

Levels of chromium and arsenic at the unsaturated zone/aquifer interface were found to be in exceeding levels of European Union and US-EPA drinking water standards, with presence of cadmium and mercury above minimum reporting values (MRVs) as reported by Slack R et al., 2007.

3.2.7 Nitrates and Phosphates

Nitrates and phosphates are essential nutrients required by plants and microorganisms for their physiological processes. However, they are considered harmful if their concentration exceeds prescribed limits in drinking water.

The BIS standards for drinking water prescribes nitrate concentration not exceeding 45 mg/L. Comparing to legacy data recorded by NEERI in 2005 showing higher concentrations of nitrates in certain locations in the range of 32 mg/L, 26 mg/L and 23 mg/L in Chinnaobulapuram, Annapanaikankuppam and Old Gummidipoondi respectively, the current study recorded lesser values of nitrates i.e. < 10 mg/L in all of the monitored locations. This indicates better agricultural management practices in the study area and its surroundings, where contamination due to inappropriate usage of fertilisers are reduced. Thus, all of samples tested were well within the drinking water limits for nitrate concentration indicating no nitrate pollution in the study area. Similar observations were made by Kumari et al.,2018 who reported that nitrate levels were well within the Indian drinking water standard limits. The reason was attributed to nitrates getting absorbed in nearby soil strata.

The assessment of phosphate concentration during 2005 and 2017 showed values lesser than 0.1 mg/ L in the present study, indicating no pollution due to phosphate concentrations in the groundwater.

3.2.8 Organic Pollution

The organic pollution in the ground water quality was assessed by monitoring the biological oxygen demand (BOD) and chemical oxygen demand (COD) in the ground water samples. *BOD* is the amount of oxygen required to biologically oxidize the organics, whereas *COD* is the amount of oxygen required to chemically oxidize organic matter in the water or wastewater. There is no prescribed limit given for BOD and COD in the BIS 10500:2012 for drinking water. However, concentrations of BOD and COD are expected to be zero or negligible in drinking water for safe consumption.

The analysis of BOD and COD in the study area had values below detectable limits showing no organic pollution in the ground water. Also, as no legacy data on BOD or COD was available in the 2005 report, no comparison with the earlier data could be made. Results reported by Hassan and Ramadan, 2005 on impacts of sanitary landfill leachate on the groundwater also showed no organic contamination around the active cells of landfill in Egypt.

3.3 Analysis of Correlation between Physico-Chemical parameters using Pearson Co-efficient

Pearson's correlation matrices were used to find relationships between two variables of the physico-chemical parameters studied. Samples showing r>0.7 are strongly correlated (Qianlin Zheng *et al*., 2017). The result of correlation analysis performed on the water quality variables are presented in Table-4. Most of the parameters tested exhibited significant correlation among each other indicating high influence on the characteristics of chemical constituents.

Table. 4. Pearson co-efficient (r) among various water quality variables

	pH	EC	TDS	Alkalinity	Hard ness	Cl-	SO$_4$	PO$_4$	NO$_3$	Ca	Mg	Na	K
pH	1.00												
EC	0.24	1.00											
TDS	0.24	1.00	1.00										
Alkalinity	0.54	0.00	0.26	1.00									
Hardness	0.28	0.35	0.44	0.33	1.00								
Cl-	0.12	0.82	0.86	0.11	0.44	1.00							
SO4	0.43	0.73	0.69	0.20	0.09	0.54	1.00						
Po4	0.08	0.61	0.61	0.02	0.17	-0.37	-0.01	1.00					
NO3	0.18	-0.23	0.23	0.04	-0.28	-0.46	-0.26	0.08	1.00				
Ca	0.13	0.73	0.73	0.13	0.83	0.85	0.32	-0.26	0.28	1.00			
Mg	0.12	0.66	0.66	0.14	0.75	0.64	0.42	0.03	0.22	0.87	1.00		
Na	0.42	0.82	0.82	0.26	0.21	0.81	0.57	0.11	0.32	0.78	0.73	1.00	
K	0.21	0.75	0.75	0.21	0.11	0.78	0.57	0.23	0.19	0.27	0.36	0.81	1.00

pH, electrical conductivity, and TDS showed positive correlation with all the parameters studied. Electrical conductivity was highly correlated with TDS, chlorides, sulphates, sodium, potassium, calcium, and magnesium etc. Subba Rao, 2002 reported that almost all analysed metals showed good correlation with conductivity, because conductivity increases with presence of metallic ions that aid oxidation-reduction reactions in groundwater aquifer system.

Calcium and magnesium presented a strong positive correlation (0.87), indicating a common source of origin. The correlation between Na-Ca (0.78) and Na-Mg was significant (0.73) showing strong cation exchange dependency between the ions. Chloride showed positive correlation with most anions and cations. The prevalence of hardness in the water was also evident from good correlation between calcium and chlorides (0.85) as observed in previous by Sana'a Odat, 2015.

3.4 Analysis of hydrochemical facies using Piper trilinear diagram:

Piper's plot was used to determine the ionic nature of the water samples collected from 23 locations (Figure.7). Based on the diagram a few inferences on the hydrochemical classification were made. It was evident that the bicarbonates and carbonates dominated the anions compared to chlorides and sulphates.

The plots also indicate a higher presence of Ca^{2+} in all the samples analysed. Using the classification scheme given in Figure 6. a &b, Piper's diagram classified all water samples into 'Mixed Ca^{2+} -Mg^{2+} - HCO_3^- type.

Despite the high alkalinity and buffering capacity of the groundwater in the study area, lesser pH (<7) observed in few sampling locations indicate possible leaching of anions from industrial discharges causing groundwater contamination.

a. Reference plot for ionic classification

b. Ionic classification of tested water
Figure 7. Piper plot showing hydrochemical classification

IV. CONCLUSION

A 3D ground water flow model created using VISUAL MODFLOW indicated that the water flow from the landfill site was predominantly towards the southeast direction. Based on predicted groundwater flow direction, downstream locations from the project site were monitored which showed that the water quality in the predicted vulnerable areas were not affected. However, slightly acidic pH values observed in the upstream locations raised concerns of possible groundwater contamination that would have been caused by illegal industrial discharges and aquifer contamination. The effect is observed to be nullified as the waterflows downstream and the acidity is neutralised with dilution and dispersion effects of water. The temporal analysis of pH values revealed that certain pockets of the study area were affected with low pH, even before the establishment of the landfill facility in 2007. The results thus suggests that the

acidification of groundwater would have been caused by effluent discharges by the industries already present in the industrial estate and cannot be attributed the operations of common hazardous waste landfill facility. This necessitates stringent monitoring actions for treated effluent disposal and increasing emphasis on zero liquid discharges, such that any impact on groundwater quality can be avoided in future.

REFERENCES

1. Abd El-Salam, M.M., Abu-Zuid, G.I., 2015. Impact of landfill leachate on the groundwater quality: A case study in Egypt. J. Adv. Res. 6, 579–586. https://doi.org/10.1016/j.jare.2014.02.003
2. Bagchi, A 1994. Design, Construction and Monitoring of Landfills. 2nd Ed. John Wiley Sons. Inc., New York.
3. Boyd, C.E., Tucker, C.S., Somridhivej, B., 2016. Alkalinity and Hardness: Critical but Elusive Concepts in Aquaculture. J. World Aquac. Soc. 47, 6–41. https://doi.org/10.1111/jwas.12241
4. Boyd, C.E., Tucker, C.S., Viriyatum, R., 2011. Interpretation of pH, acidity, and alkalinity in aquaculture and fisheries. N. Am. J. Aquac. 73, 403–408. https://doi.org/10.1080/15222055.2011.620861
5. Brisbane, S.M.P.&, 1996. Melbourne Regional Landfill Hydrogeological Assessment. Monit. landfill leachate.
6. Burge, H.A., Rogers, C.A., 2000. Outdoor allergens. Environ. Health Perspect. 108, 653–659. https://doi.org/10.1289/ehp.00108s4653
7. CPCB, 2016. "Treatment, Storage, and Disposal Facilities (TSDFs) data published by Central Pollution control Board, ENVIS Centre on Control of Pollution Water, Air and Noise, 2016, http://cpcbenvis.nic.in/tsdf.html#.
8. Chao-Shi Chen, Chia-Huei Tu , Shih-Jen Chen and Cheng-Chung Chen , Int. J. Environ. Res. Public Health 2016, 13, 467; doi:10.3390/ijerph13050467
9. Chofqi A, Younsi A, KbirLhadi E, Mania J, Mudry J, Veron A, 2004, Environmental impact of an urban landfill on a coastal aquifer (El Jadida, Morocco), Journal of African Earth Sciences, 39 (3–5), 509-516. https://doi.org/10.1016/j.jafrearsci.2004.07.013.
10. Dongo, K., Tiembre, I., Kone, B.A., Zurbrugg, C., Odermatt, P., Tanner, M., Zinsstag, J., Cisse, G., 2012. Exposure to toxic waste containing high concentrations of hydrogen sulphide illegally dumped in Abidjan, Cote d'Ivoire. Environ. Sci. Pollut. Res. Int. 19, 3192–3199. https://doi.org/10.1007/s11356-012-0823-2.
11. Et alfy and Merkel, 2006, Hadrochemical relationships and geochemical modelling of ground water in Al Arish area, North Sinai, Egypt, Journal of American Institute of Hydrology, 22, 47-62.
12. Fazzo, L., Minichilli, F., Santoro, M., Ceccarini, A., Della Seta, M., Bianchi, F., Comba, P., Martuzzi, M., 2017. Hazardous waste and health impact: a systematic review of the scientific literature. Environ. Heal. 16, 107. https://doi.org/10.1186/s12940-017-0311-8
13. Hassan A.H and Mohamed H.R, 2005, Assessment of sanitary landfill leachate characterizations and its impacts on groundwater at Alexandria, The Journal of Egyptian Public Health Association, 80 (1-2),27- 49.
14. Harbaugh, A.W.; Banta, E.R.; Hill, M.C.; McDonald, M.G. MODFLOW-2000, the U.S. Geological Survey Modular Ground-Water Model—User Guide to Modularization Concepts and the Ground-Water Flow Process; USGS Open-File Report 00-92; U.S. Geological Survey: Reston, VA, USA, 2000. 43.
15. Jothivenkatachalam J, Nithya A and Chandra Mohan S, 2010, Correlation analysis of drinking water quality in and around Perur Block of Coimbatore District, Tamil Nadu, India, Rasayan 3 (4), 649-654.
16. Kubal, M., Kočí, V., Švagr, A., Kuraš, M., Kuraš, M., 2003. Environmental impact of hazardous waste landfill breakdown, in: WIT Transactions on Biomedicine and Health. WIT Press, pp. 93–102. https://doi.org/10.2495/EHR030101.
17. Kumar, D and Alappat, B.J. 2005, Analysis of leachate pollution index and formulation of sub-leachate pollution indices. *Waste Management & Research, 23*, 230 - 239.
18. Kumari P, Amarjeet K and Gupta N C, 2018, Extent of groundwater contamination due to leachate migration adjacent to unlined landfill site of Delhi, Environmental Claims Journal, DOI: 10.1080/10406026.2018.1543825

19. Krishna Kumar S, Logeshkumaran L, Magesh N.S, Prince S. Godson, Chandrasekar N, 2015, Hydro-geochemistry and application of water quality index (WQI) for groundwater quality assessment, Anna Nagar, part of Chennai City, Tamil Nadu, India, Appl Water Sci, 5, 335–343.
20. Maiti, S.K., De, S., Hazra, T., Debsarkar, A., & Dutta, A., 2016, Characterization of leachate and its impact on surface and groundwater quality of a closed dumpsite – A Case Study at Dhapa, Kolkata, India. *Procedia environmental sciences, 35*, 391-399.
21. Manoj K., Ghosh S. and Padhy P.K. 2013. Characterization and Classification of Hydrochemistry using Multivariate Graphical and Hydrostatistical Techniques, Res. J. Chem. Sci. 3(5), 32-42.
22. McDonald, M.G.; Harbaug, A.W. A Modular Three-Dimensional Finite-Difference Ground-Water Flow Model; USGS TWRI Chapter 6-A1; United States Government Printing Office: Reston, VA, USA, 1988; 586p. Available online: http://pubs.usgs.gov/twri/twri6a1/ (accessed on 24 January 2019).
23. Misra, V., Pandey, S.D., 2005. Hazardous waste, impact on health and environment for development of better waste management strategies in future in India. Environ. Int. 31, 417–431. https://doi.org/10.1016/j.envint.2004.08.005
24. MOEF, 2016. Hazardous and Other Wastes - Ministry of Environment and Forests. The gazzate of India 1981, 1–68.
25. Monavari, S.M., Tajziehchi, S., Rahimi, R., 2013. Environmental Impacts of Solid Waste Landfills on Natural Ecosystems of Southern Caspian Sea Coastlines. J. Environ. Prot. (Irvine,. Calif). 04, 1453–1460. https://doi.org/10.4236/jep.2013.412167
26. Mariappan N V, Princeton, P., 2012. Environment assessment of industrial landfill site in Tamil nadu. Int. J. Curr. Res 4, 252–256.
27. Narendra Singh Bhandari, Kapil Nayal, 2008, Correlation study on physico-chemical parameters and quality assessment of Kosi river water, Uttarakhand, E-Journal of Chemistry, 5 (2) 342-346.
28. Piper, A.M., 1944. A graphic procedure in the geochemical interpretation of water-analyses. *Eos, Transactions American Geophysical Union*, 25(6), 914–928.
29. Press, O., 2016. Living near a landfill could damage your health, https://www.sciencedaily.com/releases/2016/05/160524211817.htm.
30. Qianlin Zheng, Teng Ma, Yanyan Wang, Yani Yana, Lu Liua, 2017,
31. Hydrochemical characteristics and quality assessment of shallow groundwater in Xincai River Basin, Northern China, Procedia Earth and Planetary Science, 17, 368 – 371.
32. Sana'aOdat, 2015, Cluster and Factor Analysis of Groundwater in Mafraq Area, Jordan, Current World Environment, 10(2), 422-431, http://dx.doi.org/10.12944/CWE.10.2.06.
33. Singh, U., Kumar, M., Chauhan, R., Jha, P.K., Ramanathan, A., & Subramanian, V, 2008. Assessment of the impact of landfill on groundwater quality: A case study of the Pirana site in western India. *Environmental Monitoring and Assessment, 141*, 309-321.
34. Slack Rebecca, Gronow Jan, Hall David and Voulvoulis Nikolaos, 2007, Household Hazardous Waste Disposal to Landfill: Using Landsim to Model Leachate Migration. Environmental pollution (Barking, Essex : 1987). 146. 501-9. 10.1016/j.envpol.2006.07.011.
35. Sunilkumar Srivastava, Ramanathan, A.L,2008, Geochemical assessment of groundwater quality in vicinity of Bhalswa landfill, Delhi, India, using graphical and multivariate statistical methods, Environ Geol, 53:1509–1528.
36. Vasudevan, D, Murugesan A. G , 2017. Hazardous Waste Management in India : Current Scenario and Future Opportunities, International Journal of Scientific Research in Science and Technology 3, 118–127.
37. Vrijheid, M., 2000. The developing brain and the environment: An introduction. Environ. Health Perspect. 108.
38. Weiner, E., 2000. National Recommended Water Quality Criteria. Applied Environmental. Chemistry. https://doi.org/10.1201/9781420032963.axb
39. Yang Y, Jiang YH, Lian XY, 2016, Risk-Based Prioritization Method for the Classification of Groundwater Pollution from Hazardous Waste Landfills, Environ Manage.58(6):1046-1058. doi:10.1007/s00267-016-0749-4.
40. Ying Li, Li J, Chen S, Diao W. 2012, Establishing indices for groundwater contamination risk assessment in the vicinity of hazardous waste landfills in China. Environ Pollut.;165:77-90. doi:10.1016/j.envpol.2011.12.042

AUTHORS PROFILE

D. Vasudevan, is a part-time Research Scholar in the Department of Environment Sciences, Manonmaniam Sundaranar University, Alwarkurichi, India. He is working as a District Environmental Engineer in Tamilnadu Pollution Control Board, Chennai. He has 30+ years of experience in environmental field and is specialized in environmental monitoring, pollution control methods, environmental regulation and compliance. He has carried out extensive research on management of hazardous wastes and has publications in peer reviewed journals.

A.G. Murugesan, is a University Grants Commission Faculty Fellow, retired Senior Professor and Head of Sri Paramakalyani Centre of Excellence in Environmental Sciences, Manonmaniam Sundaranar University, Alwarkurichi, India. He has received several State awards, has guided 43 research scholars so far, published more than 700 research papers and authored 8 books on environment. He is a fellow in 7 academies and has also served as expert member in several high-level environmental committees, including the Ministry of Environment and Forest's State-level expert appraisal committee for two consecutive terms. He is doing research in different aspects of industrial toxicology, natural resources management, environmental impact assessment, bio-remediation and bio-energy generation using microbial technologies. He has produced a biopolymer – Poly Hydroxy Butyrate B – from water hyacinth. He has to his credits two National Awards and two State awards for Environmental Protection.